

Bank of America Building Assessment

Location:
Norfolk, VA


This was an investigation of the exterior structural condition of the 2nd, 3rd and 4th floor concrete beams and columns spalls and cracks.

Owner/Client:
Nelson
114 North 2nd Street
Richmond, Virginia 23219

The purpose of this study was to perform a survey and to document cracks and spalls that were visible during the building survey. Also as part of this report, we included methods of structural repairs of the cracks and concrete spalls.

Construction Cost:
\$125,000.00

Completion Date:
October 2004



Bank of America Building Assessment

Location:

Norfolk, VA

Owner/Client:

Nelson
114 North 2nd Street
Richmond, Virginia 23219

Construction Cost:

\$125,000.00

Completion Date:

October 2004