Hotel Resort Structural Assessment and Repairs

Location:

Virginia Beach, Virginia

Owner/Client:

Confidential

Cost:

ABC Consulting, Inc. was retained by the Owners Association to perform a building assessment, a study, and recommendation for the repairs of the building's exterior walkways that include steel columns and beams that were damaged due to exposure to the salty beach air.

