7400 Granby Street Stairs

Location:

Norfolk, VA

Owner's Representative:

Cavalier Land, Inc. 234 Bute Street Norfolk, Virginia 23510

Cost:

\$22,000.00

Projected Completion Date:

2009

The owners had continuous problems with the exterior steel stairs and concrete landing. ABC Consulting, Inc. designed a new set of stairs, coated with a special marine apoxy paint to withstand the weather element. The stairs were taken down and replaced over a long weekend. On Monday morning, the employees were able to access their offices through two brand new sets of stairs.



